Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/18018UE-1841/1

Work Order Type: Weatherization Audit Name: 18018UE-1841

CLIENT INFORMATION

Client Name: Address:

Client ID: 18018UE-1841

Alt. Client ID: Hawkins

<u>AGENCY INFORMATION</u>

Agency: Upper East Tennessee Human Development Agency Agency Phone: 246-6180

Address: 301 Louis Street Fax:

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

Trailer 1990 Fleetwood has vinyl underpinning has pitched roof 14 x 70 = 940 sq.ft. Has cool seal latex on roof. Seal ducts (7)

Measures

| Measure 1 Se | al Ducts | | | Componen | ts | | | Inspected |
|--------------------|---------------------------|-------|--------|--------------|-------|-----|------------|-----------|
| Comment | | | | | | | | |
| | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Miscellaneous S | u Duct Sealing | Each | 7 | | | | | |
| 1 Insulation | Duct sealing (setup cost) | Each | 7 | | | | | |
| Other Detail | | | | | | 7 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | • | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| | Measure 2 Gene | eral Air Sealing | | | Componen | ts | | | Inspected |
|---|----------------------------------|--|----------|----------|--------------|-----------|-----|------------|-----------|
| C | c omment Awning installed | window leaky and air com | e around | I the ac | dded framing | g custome | er | | |
| | | | | | Estimated | 1 | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Labor | caulk interior windows | Each | 8 | | | | | |
| 1 | Miscellaneous Su | caulk interior windows | Each | 8 | | | | | |
| 2 | Miscellaneous Su | Seal plumbing under kitchen and bath sink | Each | 2 | | | | | |
| 2 | Labor | seal plumbing penetration under sinks | Each | 2 | | | | | |
| 3 | Miscellaneous Su | install gasket around bathtub | Each | 1 | | | | | |
| 3 | Labor | gasket missing and area around edge of tub leaky | Each | 1 | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] - | Sub Total: | |
| | Field Notes: | | | | | | | | |

| | eplace Doors Mandatory | | | Componen | ts DR2 | | ı | nspecte |
|---|---|-------------------|----------|-----------------------|----------|------|------------------|----------|
| Comment | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Labor | Replacement doors | Each | 1 | | | | | |
| 1 Doors | Replacement doors | Each | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | Magazin | e Sub Total: | |] [] | Sub Total: | |
| | | | weasur | e Sub Total. | |] | oub rotur. | |
| | | | | | | | | |
| | ghting [Family][2] | | | Componen | ots LT2 | | , | nspecte |
| | ghting [Family][2] | | | Componen Estimated | | | I Actual | Inspecte |
| Comment | ghting [Family][2] Description / Comment | Units | Qty | - | | Qty | | Inspecte |
| Comment # Material / Labor | | <i>Units</i> Each | Qty 2 | Estimated | <u> </u> | Qty | Actual | |
| Comment # Material / Labor 1 Labor | Description / Comment | | _ | Estimated | <u> </u> | Qty | Actual | |
| Comment # Material / Labor 1 Labor | Description / Comment Compact Fl13 Watt | Each | 2 | Estimated | <u> </u> | Qty | Actual | |
| Comment # Material / Labor 1 Labor 1 Lighting | Description / Comment Compact Fl13 Watt | Each | 2 | Estimated | <u> </u> | Qty | Actual | |
| Comment # Material / Labor 1 Labor 1 Lighting | Description / Comment Compact Fl13 Watt | Each | 2 | Estimated | <u> </u> | Qty | Actual | |
| Comment # Material / Labor 1 Labor 1 Lighting | Description / Comment Compact Fl13 Watt | Each | 2 2 | Estimated | <u> </u> | | Actual | |
| Comment # Material / Labor 1 Labor 1 Lighting | Description / Comment Compact Fl13 Watt | Each | 2 2 | Estimated Unit Cost | <u> </u> | | Actual Unit Cost | |
| # Material / Labor 1 Labor 1 Lighting Other Detail | Description / Comment Compact Fl13 Watt | Each | 2 2 | Estimated Unit Cost | <u> </u> | | Actual Unit Cost | |

| Measure 5 Lig | hting [Dining][2] | | | Componen | ts LT3 | | ı | Inspected |
|--|---|----------------------|----------------|---------------------|--------|------|------------------|-----------------|
| Comment | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Lighting | Compact Fl13 Watt | Each | 2 | | | | | |
| 1 Labor | Compact Fl13 Watt | Each | 2 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] , | Sub Total: | |
| Field Notes: | | | | | | | | |
| Measure 6 Lig | hting [Bathro][2] | | | Componen | | | | Inspected |
| Measure 6 Lig | | Unite | | Estimated | | Oftv | Actual | |
| Measure 6 Lig Comment # Material / Labor | hting [Bathro][2] Description / Comment Compact Fl13 Watt | <i>Units</i> Each | Qty 2 | • | | Qty | | Inspected Total |
| Measure 6 Lig Comment # Material / Labor 1 Lighting | Description / Comment | | Qty | Estimated | | Qty | Actual | |
| Measure 6 Lig Comment # Material / Labor 1 Lighting | Description / Comment Compact Fl13 Watt | Each | Qty 2 | Estimated | | Qty | Actual | |
| Measure 6 Lig Comment # Material / Labor 1 Lighting 1 Labor | Description / Comment Compact Fl13 Watt | Each | Qty 2 | Estimated | | Qty | Actual | |
| Measure 6 Lig Comment # Material / Labor 1 Lighting 1 Labor | Description / Comment Compact Fl13 Watt | Each | Qty 2 | Estimated | | Qty | Actual | |
| Measure 6 Lig Comment # Material / Labor 1 Lighting 1 Labor | Description / Comment Compact Fl13 Watt | Each Each | Qty 2 2 | Estimated | | | Actual | |
| Measure 6 Lig Comment # Material / Labor 1 Lighting 1 Labor | Description / Comment Compact Fl13 Watt | Each Each | Qty 2 2 | Estimated Unit Cost | | | Actual Unit Cost | |

| cription / Comment CU FT all refridgerator | <i>Units</i> Each Each | Qty 1 | Estimated Unit Cost | Total | Qty | Actual Unit Cost | Total |
|--|--|----------------------------------|--|--|---|---|--|
| CU FT | Each | _ | | | Qty | | Total |
| CU FT | Each | _ | | Total | Qty | Omit Cost | i Otai |
| | | ı | | | | | |
| all refridgerator | Each | | | | | | |
| | | 1 | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | - |
| | | Measur | e Sub Total: | | | Sub Total: | |
| | | | | | | | |
| [Bedroo][2] | | | Componen | ts LT1 | | , | Inspecte |
| | | | Estimated | | | Actual | |
| cription / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| npact Fl13 Watt | Each | 2 | | | | | |
| npact Fl13 Watt | Each | 2 | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | Measur | e Sub Total: | | | Sub Total: | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | [Bedroo][2] ccription / Comment mpact Fl13 Watt mpact Fl13 Watt | mpact Fl13 Watt Each Each Each | [Bedroo][2] scription / Comment Units Qty mpact Fl13 Watt Each 2 mpact Fl13 Watt Each 2 | Estimated Scription / Comment Units Qty Unit Cost mpact Fl13 Watt Each 2 | [Bedroo][2] Components LT1 Estimated ccription / Comment Units Qty Unit Cost Total mpact Fl13 Watt Each 2 mpact Fl13 Watt Each 2 | [Bedroo][2] Components LT1 Estimated ccription / Comment Units Qty Unit Cost Total Qty mpact Fl13 Watt Each 2 mpact Fl13 Watt Each 2 | [Bedroo][2] Components LT1 Estimated Actual Scription / Comment Units Qty Unit Cost Total Qty Unit Cost Impact Fl13 Watt Each 2 Impact Fl13 Watt Each |

| | <i>Measure</i> 9 Fix V | Viring Problems (Walls | s) | | Componen | ts | | ı | nspected |
|---|--------------------------|----------------------------|---------|---------|--------------|-------|------|------------|----------|
| C | comment plug-in b | ehind refrigerator in kitc | hen | | | | | | |
| | | | | | Estimated | 1 | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Labor | Labor | Each | 1 | | | | | |
| 1 | Health and Safety | Equipment | Each | 1 | | | | | |
| (| Other Detail | | | I [| | | 1 | | |
| L | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] ; | Sub Total: | |
| | Field Notes: | | | | | | | - | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | Work Or | der Gra | nd Total: | | Gran | d Total: | |